

School Upgrades & Improvements

CEDAR MILL Elementary School



For more information, visit bond.beaverton.k12.or.us or Scan QR







Security Upgrades

Installation of security cameras & increased security at entry access points





Interior Classroom Locks

Installation of new push/turn hardware





Roofing




STATUS: COMPLETE



Seismic Upgrades


Modifications to improve seismic performance





HVAC Upgrades





Electrical Upgrades

Upgraded electrical service, switchgear & panels



STATUS: COMPLETE



New Phone System

New system with building-wide safety alert capability






Playground **Improvements**

Retrofit & replacement of playground components





Window Replacement